

**ОСНОВНЫЕ РАЗМЕРЫ
КОМПЛЕКТУЮЩИХ ДГ
ЦЕНТРИРУЮЩИЕ ШАЙБЫ**

МОДЕЛЬ ДГ	ЭСКИЗ
10ГДС93	<p>Technical drawing of a centering washer (10ГДС93) showing a cross-section. Dimensions include: 3.2 (height of the first step), 17 (width of the first step), 2.5 (height of the second step), 52.2 (outer diameter), and 16.6 (width of the second step).</p>
50ГДШ83	<p>Technical drawing of a centering washer (50ГДШ83) showing a cross-section. Dimensions include: 8.7 (height of the first step), 3.8 (height of the second step), 26.5 (width of the second step), 59.6 (outer diameter), and 68 (total diameter).</p>
50ГДШ74	<p>Technical drawing of a centering washer (50ГДШ74) showing a cross-section. Dimensions include: 3 (height of the first step), 5.5 (height of the second step), 30 (width of the first step), 76 (outer diameter), and 88 (total diameter).</p>
10ГДШ63 35ГДН62 50ГДШ64 100ГДШ65	<p>Technical drawing of a centering washer (10ГДШ63, 35ГДН62, 50ГДШ64, 100ГДШ65) showing a cross-section. Dimensions include: 3.3 (height of the first step), 26.2 (width of the first step), 91 (outer diameter), 100 (total diameter), 11 (height of the second step), and 2.3 (height of the third step).</p>
100ГДШ47 150ГДШ48	<p>Technical drawing of a centering washer (100ГДШ47, 150ГДШ48) showing a cross-section. Dimensions include: 4.8 (width of the first step), 121.3 (outer diameter), 137 (total diameter), and 5.7 (height of the second step).</p>

<p>100ГДН45 150ГДН45 (шайба верхняя)</p>	
<p>100ГДН45 150ГДН45 (шайба нижняя)</p>	
<p>300ГДН44</p>	
<p>100ГДШ33</p>	
<p>150ГДШ35 200ГДШ36</p>	

<p>100ГДН32 150ГДН32 300ГДН34</p>	
<p>300ГДН39 300ГДН30</p>	
<p>1000ГДН38 600ГДН312 (шайба верхняя)</p>	
<p>1000ГДН38 600ГДН312 (шайба нижняя)</p>	
<p>400ГДН15</p>	

<p>800ГДН14 1000ГДН16 (шайба верхняя)</p>	
<p>800ГДН14 1000ГДН16 (шайба нижняя)</p>	